Inspection Report

By Sri.K. Manjunath

Retd. Executive Engineer

Name of Work: providing pothole filling at ward no12 shettyhalli sub division

B.R.No: 208/15-16

Estimate Cost: 10.00 Lakhs

Bill Amount: 9,36,824.00

Date of Inspection 21-12-2017

Observation and Conclusion:

The above said work "providing pothole filling at ward no 12 Shettyhalli Sub Div" was shown to me by the Concerned ward Engineer

The above said work is inspected by me along with the Concerned ward Engineer.

The quality of the work done is found to be Satisfactory

Ravi. N.K.
AE W-12

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: providing pothole filling at ward no12 shettyhalli sub division

Raees N.C
AE W-12

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಲೆಬ್ಬಿಹಳ್ಳ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ಕವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT

Name of Work: providing pothole filling at ward no12 shettyhalli sub division

Ravi.N.K.
AEE -12

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
ಎಸ್.ಎಂ. ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

MANJUNATH. K
DQM BE (CIVIL)
EXECUTIVE ENGINEER (RTD)
PUBLIC WORKS DEPARTMENT